

Power Connection Kit Installation Instructions

Terminator ZP-S


for use with HPT power-limiting and FP constant watt heating cables








For Power Connection (1-3 Cables), In-Line Splice Connection,
T-Splice Connection, or End Termination (1-2 Cables) Applications

| Item | Qty | Description |
|------|-----|---|
| 1 | 1 | Expediter Assembly Support Cap w/ O-ring Threaded Grommet Compressor Grommet Support Base w/ O-ring |
| 2 | 1 | Junction Box Lid |
| 3 | 1 | Junction Box Base w/ O-ring |
| 4 | 1 | Nut |
| 5 | 1 | Banding |
| 6 | 1 | RTV Tube |
| 7 | 3 | Power Connection Boots |
| 8 | 1 | Banding Guide |
| 9 | 1 | Terminal Blocks w/ DIN Rail <small>(Refer to terminal specifications for maximum allowable wire size)</small> |
| 10 | 3 | Ground Sleeves |
| 11 | 1 | Junction Box Cord |

Tools Required



Certifications/Approvals


 IP66 NEMA/Type 4X -60°C ≤ Ta ≤ +55°C
 Listed Heat Tracing Cable System 137M
 Ordinary & Hazardous Locations
 Class I, Division 2, Groups A, B, C & D
 Class II, Division 2, Groups F & G, Class III
 Class I, Zone 1, AEx e II T4/T6
 Ex e II T4/T6
 0539  II 2 G & D EEx e II T4/T6  01ATEX0021995

Warnings


- Due to the risk of electrical shock, arcing and fire caused by product damage or improper usage, installation or maintenance, a ground-fault protection device is required.
- Installation must comply with Therman requirements and be installed in accordance with the NEC, CEC, or any other applicable national and local codes.



- Component approvals and performance ratings are based on the use of Therman specified parts only. User supplied power connection fittings must be European certified for EEx e or UL Listed or certified for AEx e (North America only).
- De-energize all power sources before opening enclosure.
- Keep ends of heating cable and kit components dry before and during installation.



1. Locate bus connection and cable as shown. Cut end of cable at angle to aid in piercing grommet. Leave additional cable for expansion loop. See pages 11-12 for multiple cable installation tips.




2. Insert cable into expediter. If mounted on bottom of pipe, punch out weep hole.




3. Slide expediter toward pipe and route cable through support base entry.




4. Insert banding guide into expediter and snap into place.




5. Mount expediter to pipe using pipe band. Do not band over cable.




6. Cut off end of cable.




7. Cut and remove overjacket. Do not cut metallic braid.



8. Separate braid strands at edge of overjacket and pull cable through opening in braid. Twist braid into a pigtail. Trim ends of braid.




9. Cut and remove primary insulation jacket.




10. Cut and remove fiberglass braid. Omit this step for FP cable.




11. Cut and remove heating element and fiberglass overlay (FP cable only). Push any remaining heating element wire under the primary insulation jacket.




12. Cut and remove pairing jacket. Do not cut bus wire insulation.




13. Remove insulation from ends of bus wires.



14. Apply a liberal amount of RTV sealant to cable. Slide boot onto the end of the cable.



15. Slide green/yellow ground sleeve over twisted braid.



16. Push excess cable back through expediter. Tighten cap securely. Tape cable expansion loop to pipe.




17. Using dimple molded into side of junction box base to locate center of hole, drill for user supplied power connection fittings per manufacturer's recommendations (if necessary).




18. Mount junction box base on expediter. Make sure to align slots to properly orient junction box base.




19. Install power connection fittings (user supplied) and pull in power and ground wires (if necessary).




20. Install quick mount terminal blocks.




21. Complete system wiring. Terminal set screws shall be tightened to a torque value of 1.4 Nm (12.4 lb-in). See page 13 for wiring details.




22. Install junction box lid and twist hand tight. Insert screwdriver into ratchet slots located on side of junction box base.




23. Use screwdriver to ratchet on junction box lid. Lid will rotate 30 degrees.




24. Lid latch mechanism fully engaged.




A1. Locate bus connection and cable as shown. Cut end of cable at angle to aid in piercing grommet. Leave additional cable for expansion loop.




B1. Locate bus connection and cable as shown. Cut end of cable at angle to aid in piercing grommet. Leave additional cable for expansion loop.




A2. Insert two cables into expediter.




B2. Insert three cables into expediter.




B3. Mount expediter with three cables. Do not band over cable.




C1. Power Connection (1 to 3 Cables)



C2. In-Line Splice and T-Splice



C3. End Termination (1 to 2 Cables)
Remove jumpers for 2 cable terminations.



Form No. 50820 (08/25/04)



Thermon Manufacturing Company

100 Thermon Drive • P.O. Box 609 • San Marcos, Texas 78667-0609
Phone: (512) 396-5801 • Fax: (512) 396-3627 • 1-800-820-HEAT
www.thermon.com