

TracePlus™ PCA


Power Connection Kit

INSTALLATION PROCEDURES

PCA-H for USX, BSX, HTSX, KSX, HPT, FP

PCA-V for RSX, VSX-HT

For Power Connection, In-Line Splice Connection,
T-Splice Connection, or End Termination Applications




TracePlus™ PCA

The following installation procedures are suggested guidelines for the installation of termination connection systems. They are not intended to preclude the use of other methods and good engineering or field construction practices.

Receiving, Storing and Handling

- 1. Inspect materials for damage incurred during shipping.
- 2. Report damages to the carrier for settlement.
- 3. Identify parts against the packing list to ensure the proper type and quantity has been received.

Kit Contents




Item	Quantity	Description
1	1	Expediter Assembly Locknut Gasket 1" NPT Threaded Cap Grommet Expediter Base
2	1	Junction Box Base with Cover
3	2	Banding

Order Separately


PETK Power and End Termination Kits (per cable)

- PETK-1D for BSX, RSX, VSX-HT
- PETK-2D for KSX, HTSX, USX
- PETK-3D for HPT, FP



Item	Quantity	Description
1	1	RTV Tube
2	1	Power Connection Boot
3	1	End Cap
4	1	Tape Strip (PETK-3D Only)
5	1	End Termination Caution Label
6	1	GRW-G Grommet (PETK-3D Only) not used for TracePlus Kits

Dimensions



Installation Precautions


- To minimize the potential for arcing and fire caused by product damage or improper installation use ground-fault protection. The National Electrical Code (NEC) and Canadian Electrical Code (CEC) require ground-fault protection of equipment for each branch circuit supplying electric heat tracing.
- Installation must comply with Thermon requirements and be installed in accordance with the NEC, CEC, or any other applicable national and local codes.
- Component approvals and performance ratings are based on the use of Thermon specified parts only. User supplied power connection fittings must be listed or certified for intended use.
- De-energize all power sources before opening enclosure.
- Keep ends of heating cable and kit components dry before and during installation.

Certifications/Approvals




IP65 NEMA/Type 4X
Ordinary & Hazardous Locations
Class I, Division 2, Groups A, B, C, & D
Class II, Division 2, Groups F & G, Class III


Tools Required




INSTALLATION PROCEDURES



1a. For one, two or three cables. Locate bus connection (HPT and FP only) and cable as shown. Cut end of cable at angle to aid in piercing grommet. Leave additional cable for expansion loop.



1b. Two cables.



1c. Three cables.



2a. For one, two or three cables. Insert cable into expediter, grommet, and NPT threaded cap.




2b. Two cables.



2c. Three cables.




3. Slide expediter toward pipe and route cable through base, grommet, and NPT threaded cap.




4. Mount expediter to pipe using pipe band. Do not band over cable.




5. Terminate cable with appropriate PETK termination kit. Refer to PETK installation instructions.



- 6.** Mount junction box on expediter using gasket and locknut provided.




- 7.** Install power connection fittings (supplied by others) and pull in power and ground wires. Drill junction box for user supplied connection fitting.




- 8.** Complete system wiring. (Shown with optional terminal block, connections may be prepared using wire nuts by others).


Typical Wiring Details, Shown with Optional Terminal Block




Power Connection (1 to 3 Cables).



In-Line Splice and T-Splice



End Termination (1 Cable Only)



- 12.** Install junction box lid using 4 captive screws.

