

6th Mar, 2025

Announcing the release of Genesis Panel Firmware v1.7.2

Release Category: Maintenance

Thermon continues to focus on advancing the efficiency of Heat Trace Asset Management by making continuous improvements to the Controls & Monitoring solutions portfolio. As a part of Thermon's Digitization initiative and our commitment to providing a great experience to our customers, we release new features/fixes on our products on a regular basis.

This release is for the latest version of the Genesis Panel firmware.

Resolved Issues

- Incorrect temperature readings were being measured by the DTM modules in some cases due to a firmware bug.

Note: This version of the Genesis Controller firmware must be used with TraceNet Sync v1.7.0 or above.

Thermon highly recommends all our customers upgrade the Genesis panels in their network to the latest firmware version for enhanced experience. Please work directly with our field services or product management team to facilitate the upgrade.

Thermon software download portal: <https://www.thermon.com/software-download/>

In case of any issues, please report them at [Genesis Controller™ | Thermon](#) using the 'REPORT ISSUE' link on the page or send an email to ask.me@thermon.com.

Rohit Jain

Senior Product Manager – Controls & Monitoring